

9204D17 D17"H21"L4



install your chandelier. Please read all instructions carefully and thoroughly. If you have any questions please fell free chandelier for our customers. Our master craftsmen and designer pride themselves on their attention to detail. We are dedicated to providing the finest quality crystal Enclosed, are detailed instructions on how to properly to call our toll free CHANDELIER HOTLINE AT: prompt, efficient service is our priority.

1-888-388-3390 (L) $_{c}$ (L) $_{U}$ $_{U}$ $_{U}$





9204 D17"H21"L4

WARNING!!!

CONTENTS ARE FRAGILE HANDLE WITH CARE

and installation. excersise extreme caution during unpacking of this chandelier are very delicate. Please The metal frame and crystal components

WARNING!!!

After passing the main electrical wire through the 10mm pipe and connecting the pipe to the main body top connector, place all remaining pieces as shown in numerical order and in the orientation depicted. Refer to the parts list to avoid confusion between parts. The part numbers coincide.

- Rated 110-1807/60Ez, bulb 40W maximum
 Care should be taken to avoid demage to the surface of lighting and wire, wearing gloves is recommended when installing.

3. Connect black or red wire of the lighting to live wire and white or blue wire to neutral wire

- and double colored (or bare copper) wire to ground wire.

 4. Never install lighting on demp ceiling, the room should be dry and well ventilated.
- 5. Keep lighting eway from soid, alkali and other corrosive chemical or gas, clean the lighting with
- Installation must be carried out by qualified electricism only.Disconnect the power before installing cleaning and replacing lighting.


clean soft cloth only.


- 9. Firmess must be secured when installing ceiling tube, chain, pipe and other connecting parts. 8. Never cover the lighting when power is connected.
- 10. Care should be taken to avoid demage when installing glass parts.
 11. All electrical components must be installed by a licensed electrician and in accordance with the National Electrical Code and the appropriate local electrical codes. Make sure that

14mm*6pcs

before doing any installation the electrical supply to the chandellier is turned off at the main fuse or circuit breaker

Crystal Dressing Instructions





Ч	Н	Ħ	G	ਸ	H	D	ဂ	В	A	No
4 strings	4 strings	1 strings	4 strings	4 strings	16 strings	8 strings	6 strings	6 strings	6 strings	Quantity


2

9204 D17"H21"L4

Diagram **Crystal Dressing**



When dressing the chandelier with the crystals please remembe to wear either rubber or cotton loves. So as to prevent any mage or smudging on the crystals.



Connect both ends of J with G Connect both ends of B with A 8

Connect both ends of I with F

9204 D17"H21"L4

CANOPY PARTS LIST

ZA: Existing Electrical Box (not supplied)



ZB:Crossbar



ZC:Crossbar Screws x 2(not supplied)



ZD:Canopy lock



ZE:Canopy



ZF:Metal Ring












ZJ:Electric Main



ZK: Junction Caps



CANOPY INSTALLATION DIAGRAM



9204 D17"H21"L4

Frame Assembly Instruxtions

Please read all instructions carefully. Before you proceed to install, make sure that the power supply is tamed off and off until installation is complete. Please note that each part has been assigned a letter. Please proceed in alphabetical order.

- 1. Install (Cast Canopy)01 to the electric Box and wire properly.
- .using (Grourd Screw)04, Connect the Loose (chain Connector)02 on the (All thread)10.
- . Apply (Scroll Arm)03 to (Round Metal Cover)05 using (Ground Screw)04.
- 4. Loose the screw from (All thread) 26, apply (Cast Bottom Finial) 27 on the (All thread) 26.
- 5. Dressing Crystal using Diagram provided

The end!

8

Fram Parts List

19-All thread анинини 24-Nut



25-Bottom Cover

21-All thread

26-All thread

22-Spring Seat

27-Cast Bottom Finial

23-Set Screw

9204 D17"H21"L4

CANOPY INSTALLATION INSTRUCTIONS

off until installation is complete. Please note that each part has install, make sure that the power supply is tamed off and been assigned a letter.Please proceed in alphabetical order. Please read all instructions carefully. Before you proceed to

ZA. Junction Box (not supplied)

ZB. Crossbar

ZC. Crossbar Screws

ZE. Canopy ZD. Canopy Loop

ZF. Metal Ring

ZG. Chain

ZI. Canopy loop ZH. Ground Wire

ZJ. Electric loop

ZK. Junction Caps

1. Attach the Crossbar (ZB) to the Junction Box (ZA) using the two already be in your box. crossbar screws (ZC) which are not supplied and should

2. Slide the Metal Ring(ZF) back up over the canopy(ZE) pass the canopy loop(ZD)through canopy(ZE), connect with the threaded pipe underside of the crossbar.

3. Pass the electric loop(ZJ) and ground wire (ZH) through the chain(ZG), junction box(ZA) where you can make the appropriate connections. crossbar(ZB)until the end of the electric Loop(ZJ) reaches the the Metal Ring(ZF), the canopy(ZE), the canopy loop(D) and the

4. Be sure when connecting the

5. Stow the excess wire in the junction box (ZA). wire use electrician approved junction caps(ZK)

6. Raise the canopy (ZE).

7. Metal Ring(ZF), attach canopy(ZE) to ceiling, slide Metal Ring(ZF) over canopy loop(ZD) and hold the canopy(ZE).

3



9204 D17"H21"L4 16 6 7 4 3 20 21 22 15 Frame Assembly Diagram 9 2 2 2 2 **%** 9204 D17"H21"L4 05-Round Metal Slive 02-chain Connector 01-Cast Canopy 04-Ground Screw 03-Scroll Arm Fram Parts List 06-Cast Column Cover 09-Top Cover 10-All thread 08-Mid Column 11-Set Screw 8 18-Cast Bobeche 17-Cast Socket 13-Sleeve cover 12-Cost Column 15-Set Screw 16-Washer 14-Socket 0